



[evolutionm.net](http://forums.evolutionm.net/index.php) (<http://forums.evolutionm.net/index.php>)

- [Vishnu Performance - California](http://forums.evolutionm.net/forumdisplay.php?f=85) (<http://forums.evolutionm.net/forumdisplay.php?f=85>)

- - [Conditional How-To: Lean-Run Protection](http://forums.evolutionm.net/showthread.php?t=204812) (<http://forums.evolutionm.net/showthread.php?t=204812>)

shiv@vishnu

Jun 5, 2006 08:36 PM

Conditional How-To: Lean-Run Protection

To all those beta guys out there, here's how you set-up your Xede for lean-run protection. It's real easy to do and will pay off the first time your FPR signal line blows off or your methanol system clogs or runs out of fuel.

First step is to go to your MAF/Fuel table. Right-click and select "Edit this map". You will see this:

The conditional set-up should be disabled to start with. It should look like this: